

Part No.

XTHA-KIT4

(1) 1/8", (1) 1/4", (1) 1/2" FNPT Quick-connect S.S. x Male Quick-test XT adapters, nylon bag

Adapt to pressure gauges or transmitters with Male NPT connections up to 10,000 psi without a wrench or thread sealant



XTHA-KIT4

Included Items

- Reference Connection - 1/8" female NPT Quick-connect x male Quick-test XT, S.S. (XTHA-1FS0-QD)
- Reference Connection - 1/4" female NPT Quick-connect x male Quick-test XT, S.S. (XTHA-2FS0-QD)
- Reference Connection - 1/2" female NPT Quick-connect x male Quick-test XT, S.S. (XTHA-4FS0-QD)
- Bag - Zippered bag to hold hose and adapters, nylon (SM-0084)

Specs/Attributes

Country of origin	USA
Weight	4.98 oz / 140 grams
Dimensions	H: 6.5 in (16.51 cm) x W: 6.5 in (16.51 cm) x D: 1 in (2.54 cm)

Reference Connection XTHA-4FS0-QD

Country of origin	USA
Dimensions A	0.00 in / 0.00 mm
Dimensions B	0.00 in / 0.00 mm
Has Check Valve	No
Materials	Stainless Steel
Max Operating Temperature	400 °F / 205 °C
Max Pressure	10000 PSI / 700 bar / 70 MPa
Min Operating Temperature	-15 °F / -26 °C

Reference Connection XTHA-4FS0-QD

Seal Materials	Teflon, Viton
Connector End 1	1/2" Female NPT (ASME B1.20.1)
Connector End 2	Male Quick-test XT
Weight	8.42 oz / 240 grams
Dimensions	H: 1.89 in (4.8 cm) x W: 1.6 in (4.06 cm) x D: 1.6 in (4.06 cm)

Bag SM-0084

Materials	Zippered Nylon
Country of origin	USA
Weight	3 oz / 85 grams
Dimensions	H: 6.5 in (16.51 cm) x W: 6.5 in (16.51 cm) x D: 0.5 in (1.27 cm)